

**Comprehensive Fire Safety, Casualty  
Safety and Sanitation Report - Non-completes**

**District: LEE County Schools**

**Local Municipal Inspection Authority:**

Fort Myers Fire District  
1825 Hendry Street  
Fort Myers, 33901  
239 321-7350

**Fiscal Year:** 2024-2025

**Inspection Date:** 11/18/2024

**Scheduled Reinspection Date :** 01/22/2025

**Actual Reinspection Date :** 02/14/2025

**Office of:**

Lee County Public Education Center  
2855 Colonial Blvd  
Fort Myers, 33966  
239 337-8590

**Print Date:** 02/14/2025

**Facility:** Fort Myers Technical College

**FISH #:** 36-00034-00034

**Address:** 3800 Michigan Avenue  
Fort Myers, 33916  
239 344-4544

**Facility Type:** Other (Vo-Technical School)

**Area:** E

**District Inspector:** Joshua Agilar

**Inspector #:** 185284

**Legend:**

**Priority:**

- 1 = Serious
- 2 = Violation

**Category:**

- A = Fire Safety
- B = Casualty Safety and Sanitation

**Citations from Code:**

- 69A-58 = Fire Safety Standards and Requirements for Educational and Ancillary Facilities and Plants (F.A.C.)
- SREF = State Requirements for Educational Facilities (2012)
- NFPA = National Fire Protection Association

**Deficiency Type and Corrective Action Planned and Schedule:**

- O = Operation of Plant -- School Responsibility to complete within 30 days of receipt of inspection report
- M = Maintenance of Plant -- 30 days to complete after Inspection Date
- C = Capital Outlay -- June 30 of fiscal year or becomes part of Plan of Correction

**Complete:**

- Y = Yes
- N = No

**Fire Exit Drill Requirements:**

NFPA 101-15.7.2.3 (1): At least one fire exit drill shall be conducted every month the facility is in session.

NFPA 101-15.7.2.3 (3): One additional fire exit drill shall be required within the first 30 days of operation.

Required Exit Drills Completed as of this inspection date.

**Certifications of Compliance with Florida Statutes:**

District **HAS** complied with section 1013.12(2)(d) of Florida Statutes regarding plan of action and schedule for correction of each fire safety deficiency.

Local Authority **HAS** complied with section 1013.12(2)(d) of Florida Statutes regarding plan of action and schedule for correction of each fire safety deficiency

**Signatures:**

Facility Admin Acknowledging Awareness of Discovered Deficiencies and Verifying Required Emergency Drills: \_\_\_\_\_ Date: \_\_\_\_\_

School District Inspector Reporting Deficiencies: \_\_\_\_\_ Date: \_\_\_\_\_

Local Municipal Inspection Authority Inspector Reporting Deficiencies (if Applicable): \_\_\_\_\_ Date: \_\_\_\_\_

**Comprehensive Fire Safety, Casualty  
Safety and Sanitation Report - Non-completes**

Date Inspected: 11/18/2024

Facility: Fort Myers Technical College

Fiscal Year: 2024-2025

Citation	Priority	Category	Bldg	Room	Deficiency Description and Corrective Action Required  Inspector's Notes, if any.  Location of Deficiency, if specified.	Deficiency Type	Prev Years Cited	Complete
						Est Complet Date		SFM Code
SREF 5 (8) (c) 1	2	B	001	01B	Hardware on door can not be lockable from the inside.  <i>Unisex bathroom door cannot be locked from the inside.</i>	M	0	N 299
69A-58-0081	2	A	001	03D	Install heat/smoke detector  <i>Several unsupervised storage rooms have no fire detection. 1-03D, 1-02, 7-02F, 8-05A.</i>	M	0	N 405
NFPA 720-10.6.5.4	2	A	004	001	Install circuit breaker lockout clip on the fire alarm breaker  <i>Auto body shop electrical panel behind caged area.</i>	M	0	N 403
SREF 5 (9)	2	B	008	21C	Ceiling missing or damaged.  <i>Electrical room ceiling has hole in ceiling.</i>	M	0	N 399
NFPA 101-7.2.1.5.1	2	A	009	002	Door drags on frame - must be adjusted to open freely.  <i>Cafe exterior egress door is dragging making it difficult to open and close.</i>	M	0	N 299
SREF 5(3)(b)2	2	B	998	998	Adjust signage to prevent creating a visual barrier.  <i>Stop signs around parking lot are damaged or fallen over from Hurricane Milton.</i>	M	0	N 1399

Number of Serious Fire Safety Citations: 0

Total number of Fire Safety, Casualty Safety and Sanitation Citations: 6

Total Number of Already Completed and Validated Items: 0